

To Mill Creek

Butler Lateral

Stayton/Power canal headgates and fish screen structure unused water returns to north branch via spill dam channel shown in orange

Salem ditch headgate

Main irrigation headgates

Lower Bennett Dam


Tailracer Barrier

Geren Island

NS side channel and sewer treatment plant discharge

Upper Bennett Dam

Legend



— North Santiam River

< Flow direction